



cofe

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Applicant:

David Bassett and Gary Browning

Patent No.: 6,859,853

Issued: February 22, 2005

Serial No.: 09/846,960

Filed: May 1, 2001

For: METHOD AND APPARATUS  
FOR DRIVING SIGNALS ON  
A BUS

§ Atty. Docket No.: 5681-47400

§ Group Art Unit: 2112

§ I hereby certify that this correspondence is being deposited with the  
§ U.S. Postal Service as First Class Mail in an envelope addressed to:  
§ Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-  
§ 1450, on the date indicated below:

B. Noel Kivlin  
Signature of Representative

5-26-05

Date

Signature

Certificate  
JUN 06 2005  
of Correction

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Dear Sir:

Transmitted herewith for filing in the captioned case are the following:

- (1) Form PTO-1050, **submitted in duplicate**. Errors which occur at important points in the captioned patent or which may otherwise affect the understanding or interpretation of the patent are thereon corrected.
- (2) A return postcard to acknowledge receipt of these materials. Please stamp and return this postcard to the undersigned.

All of the errors shown in PTO-1050 are due to Patent Office oversights. A Certificate of Correction is requested under 35 U.S.C. §254. Applicants believe that no fees are required, however, should any fees be required, please deduct them from Meyertons, Hood, Kivlin, Kowert & Goetzel, P.C. Deposit Account No. 501505\5681-47400/BNK.

Respectfully submitted,



B. Noël Kivlin  
Reg. No. 33,929

Meyertons, Hood, Kivlin,  
Kowert & Goetzel, P.C.  
P.O. Box 398  
Austin, Texas 78767-0398  
(512) 853-8840

Date: 5-26-95

UNITED STATES PATENT AND TRADEMARK OFFICE

**CERTIFICATE OF CORRECTION**

PATENT NO.: 6,859,853

DATED: February 22, 2005

INVENTORS: David Bassett and Gary Browning

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 9,

Line 10, please delete "controllably delivery signals" and substitute -- controllably delivering signals --.

Column 9,

Line 14, please delete "being driven thereon;" and substitute -- signal being driven thereon; --.

Column 10,

Line 19, please delete "on the second bus;" and substitute -- on the second bus segment; --.

-----  
MAILING ADDRESS OF SENDER:

B. Noël Kivlin, Esq.,  
MEYERTONS, HOOD, KIVLIN, KOWERT & GOETZEL, P.C.  
P.O. Box 398  
Austin, Texas 78767-0398

PATENT NO. 6,859,853

No. of add'l. copies

**Certificate of Correction (PTO Form 1050)**

JUN 6 2005